ABSTRACT

By examining scrub mark properties (such as position and size) directly, the performance of a wafer probing process may be evaluated. Scrub mark images are captured, image data measured, and detailed information about the process is extracted through analysis. The

5   information may then be used to troubleshoot, improve, and monitor the probing process.